

FILED

Date: 2/22/07 By: JC

This survey consists of:

Map: #

Narrative:

Corner Rpt: CS 65/60-3

OREGON CORNER RESTORATION FORM

Section 5 Township 28S Range 4W

County DOUGLAS Date 5-9-06

DOUGLAS COUNTY SURVEYOR

Corner Designation

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. \_\_\_\_\_

Monument(s) & Accessories Found: (Condition and Source)

1967 BLM IPBC


BTs: 18" FIR S66W 53<sup>±</sup> GONE

50" FIR N68W 14<sup>±</sup> GOOD CONDITION - HEALED FACE

FENCE STAPLED TO EAST SIDE OF BT

Monument Detail

Sketch



Monument Set (Procedures and Description)

New Accessories

BT: 9" MYRTLE N22E 21<sup>±</sup> SCRIBED "DLC BT"

Location & Comments

OLD FENCE RUNNING

N-S 15' WEST

Compass Declination 18 1/2°

Firm/Agency ROSEBURG

FOREST PRODUCTS

Address PO Box 1088

ROSEBURG OR 97470

Party Chief Bill Olson

Notes \_\_\_\_\_

Witness KEN COBLE

Surveyor's Seal

REGISTERED PROFESSIONAL LAND SURVEYOR

Mark F. Smalley  
OREGON  
JULY 26, 1988  
MARK F. SMALLEY  
2354

Renews 6/30/08

C.S. File No 65/60-3