

CORNER REPORT FORM

Section 20 Township 26S Range 3W

Douglas County Date 3-07

CORNER DESIGNATION 240300

1/4 29
30

Condition Report only

Not Found
Renewed
Unrecorded
Surveyed In
Referenced out

FILED

Date: 4-3-07 By: XC

This survey consists of:

Map: _____

Ne to Sw: _____

Corner 65/60-18

DOUGLAS COUNTY
SURVEYOR

Previous Renewals/Surveys, etc:

M-140-45

Monument(s) & Accessories Found: (Condition and Source)

Fd GLD BRASS CAP
18" CEDAR STAMP N 36 E 49⁴ FT
20" CEDAR STAMP S 35 W 36² FT
27" CEDAR STAMP S 33 W 15² FT
5" FIR N 20 E 4.4 FT VIS SCRIBES
5" FIR S 85 E 5² FT VIS SCRIBES

Monument Detail

Sketch

Monument Set (Procedures and Description)

New Accessories

Location & Comments

Compass Declination

Firm/Agency: i.e. Engineering, Inc.

Address: 505 SE Main
Roseburg, OR 97470

Party Chief: M. Fromm dahl

Notes:

Witness:

C.S. File no 65/60-18

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Ronald A. Quimby
OREGON
JULY 14, 1978
RONALD A. QUIMBY
1634

EXP 12-31-08