

FILED

Date: 1-27-2009 By: JC

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: 65/66-4

OREGON CORNER RESTORATION FORM

Section 11 Township 25 South, Range 7 West

County Douglas

Date 22 January 2009

DOUGLAS COUNTY
SURVEYOR

Corner Description

N1/16 Corner

Sections 10, 11

Condition Report Only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

Previous Renewals / Surveys, etc.

Monument (s) & Accessories Found: (Condition and Source)


Found 3-1/4" BLM brass cap dated 1958 with the following accessories:

Record W. Fir bearing S14-1/2°W 62.0' down, out of position

Record W. Fir bearing N69-1/2°E 34.0' not found

Monument Detail

Sketch



Monument Set (Procedures and Description)

None

New Accessories

19" D. Fir bears N57°W 8.7' – blazed, scribed "N1/16 S10 BT"

19" D. Fir bears S4°E 10.9' – blazed, scribed "N1/16 S11 BT"

Location & Comments

Corner has steel post adjacent to it.

All BT's have red painted bands and yellow tags.

Compass Declination 17° East

Firm/Agency Ward NorthWest Inc.

Address P.O. Box 105
Florence, OR 97439

Party Chief Ron Rice

Notes _____

Witness Josh Reed

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Ronald L. Rice

OREGON
JULY 9, 2002
RONALD L. RICE
54633LS

RENEWS: 12-31-2010

C.S. File No 65/66-4