

OREGON CORNER RESTORATION FORM

Section 20 Township 23 South, Range 6 West
County Douglas Date 28 January 2009

FILED
Date: 2-10-2009 By: SC
This survey consists of:
Map: _____
Narrative: _____
Corner Rpt: 65/66-5
DOUGLAS COUNTY
SURVEYOR

Corner Description

NW 1/16 Corner
Section 20

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals / Surveys, etc.

Monument (s) & Accessories Found: (Condition and Source)

Found 3-1/4" BLM brass cap dated 1994 with the following accessories:

- 15" D. Fir bears S34°E 27.1' – healed face
- 18" D. Fir bears N34°W 36.3' – healed face

Monument Detail

Sketch

NW 1/16 S20

1994

Monument Set (Procedures and Description)

None

New Accessories

None

Location & Comments

Corner has steel post _____ Compass Declination 17° East
adjacent to it. _____ Firm/Agency Ward NorthWest Inc.
All BT's have red painted _____
bands and yellow tags. _____ Address P.O. Box 105
_____ Florence, OR 97439
_____ Party Chief Ron Rice
_____ Notes _____
_____ Witness Josh Reed

Surveyor's Seal



RENEWS: 12-31-2010

C.S. File No 65/66-5