

FILED

Date: 2-10-2009 By: JC

This survey consists of:

Map: \_\_\_\_\_

Narrative: \_\_\_\_\_

Corner Rpt: 65/66-7

OREGON CORNER RESTORATION FORM

Section 24 Township 23 South, Range 5 West  
County Douglas Date 3 February 2009

DOUGLAS COUNTY  
SURVEYOR

Corner Description

1/4 Corner  
Sections 13, 24

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals / Surveys, etc.

Monument (s) & Accessories Found: (Condition and Source)

Found 3-1/4" BLM brass cap dated 1991 with the following accessories:

- 20" Fir bears N 42° W 24.4' healed face
- 24" Fir bears S 63° W 22.4' healed face
- 11" W. Fir bears S 49° E 11.7' partially healed face
- 12" Chinquapin bears N 68° W 17.7' open face

Monument Detail

Sketch

T23S R5W  
S13  
1/4 \_\_\_\_\_  
S24  
1991

Monument Set (Procedures and Description)

None

New Accessories

None

Location & Comments

Corner has steel post \_\_\_\_\_ Compass Declination 17° East  
 adjacent to it. \_\_\_\_\_ Firm/Agency Ward NorthWest Inc.  
All BT's have red painted  
bands and yellow tags. \_\_\_\_\_ Address P.O. Box 105  
 \_\_\_\_\_ Florence, OR 97439  
 \_\_\_\_\_ Party Chief Ron Rice  
 \_\_\_\_\_ Notes \_\_\_\_\_  
 \_\_\_\_\_ Witness Josh Reed

Surveyor's Seal



RENEWS: 12-31-2010

C.S. File No 65/66-7