

FILED

Date: 2-20-2009 By: JC

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: 65/66-10

OREGON CORNER RESTORATION FORM

Section 16 Township 23 South, Range 8 West

County Douglas

Date 18 February 2009

DOUGLAS COUNTY
SURVEYOR

Corner Description

NW Corner

Section 16

Condition Report Only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

Previous Renewals / Surveys, etc.

Monument (s) & Accessories Found: (Condition and Source)

Found 3-1/4" GLO brass cap dated 1958 with the following accessories:

44" D. Fir snag bears N 12° E 150.5' visible scribing

17" Hemlock bears S 74° E 18.4' healed face (Record W. Fir)

16" D. Fir bears N 50° E 11.3' healed face


23" D. Fir bears N 42° W 19.7' healed face

26" W. Fir bears S 57-1/2° E 195.4' healed face

Monument Detail

Sketch

T23S R8W



Monument Set (Procedures and Description)

None

New Accessories

None

Location & Comments

Corner has steel post adjacent to it.

Compass Declination 16° East

Firm/Agency Ward NorthWest Inc.

All BT's have red painted bands and yellow tags.

Address P.O. Box 105

Florence, OR 97439

Party Chief Ron Rice

Notes _____

Witness Josh Reed

Surveyor's Seal



C.S. File No 65/66-10