

OREGON CORNER RESTORATION FORM

Section 16 Township 23 South, Range 8 West
County Douglas Date 18 February 2009

FILED
Date: 2-20-2009 By: JC
This survey consists of:
Map: _____
Narrative: _____
Corner Rpt: 65/66-11
DOUGLAS COUNTY
SURVEYOR

Corner Description

1/4 Corner
Sections 9, 16

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals / Surveys, etc.


Monument (s) & Accessories Found: (Condition and Source)

Found 2-1/2" Douglas County brass cap dated 1966 with the following accessories:

- 40" D. Fir bears S 31° W 25.7' healed face
- 28" Hemlock bears N 67-1/2° W 58.9' healed face
- 43" D. Fir bears S 58° E 16.4' healed face
- Unrecorded 25" D. Fir bears N 26° W 29.0' healed face

Monument Detail

Sketch



Monument Set (Procedures and Description)

None

New Accessories

None

Location & Comments

Corner has steel post _____ Compass Declination 16° East
adjacent to it. _____ Firm/Agency Ward NorthWest Inc.
All BT's have red painted
bands and yellow tags. Address P.O. Box 105
_____ Florence, OR 97439
_____ Party Chief Ron Rice
_____ Notes _____
_____ Witness Josh Reed

Surveyor's Seal



RENEWS: 12-31-2010

C.S. File No 65/66-11