

MAP OF SURVEY

LOCATED in the NE 1/4 of Section 36,
T. 29 S., R. 4 W., W.M. Douglas Co., Oregon.

January 12, 2009

SURVEYED FOR: *SENECA JONES TIMBER CO.*
P.O. BOX 2129
ROSEBURG, OREGON 97470

SURVEYED BY: *DAVID EDWARDS LAND SURVEYING*
P.O. BOX 361
OAKLAND, OREGON 97462
PHONE : (541) 459-0512

FILED
Date: 1-15-2009 By: JC
This survey consists of:
Map: C.S. 65/67-1
Narrative: _____
Corner Rpt: _____
DOUGLAS COUNTY
SURVEYOR

REGISTERED
PROFESSIONAL
LAND SURVEYOR
David A. Edwards
OREGON
JULY 26, 1988
DAVID A. EDWARDS
2339
RENEWS 12/31/09

LEGEND

⊙ INDICATES B.L.M. OR COUNTY SURVEYOR BRASS CAP FOUND.

() DENOTES RECORD DATA PER B.L.M. RESURVEY.

————— INDICATES BOUNDARY BLAZED & POSTED THIS SURVEY.

SCALE: 1" = 600'

BASIS OF BEARINGS: B.L.M. RESURVEY AS SHOWN.

NARRATIVE

THE PURPOSE OF THIS SURVEY IS TO MARK A PORTION OF THE EAST LINE OF SECTION 36 AS SHOWN. A RANDOM TRAVERSE WAS RUN BETWEEN CONTROLLING CORNERS AND OFFSETS MADE TO TRUE LINE. MARKING WAS DONE BY BLAZING TREES ON EACH SIDE OF LINE, BY SETTING 6 FOOT STEEL POSTS ALONG THE LINE AT INTERVALS OF 200 FEET OR LESS AND BY HANGING LIBERAL AMOUNTS OF RED FLAGGING ALONG THE TRUE LINE.

FIELD CREW: BRANT MILLER AND ERIC SPRINKLE.

EQUIPMENT: NIKON TOTAL STATION.

COMPUTATIONS AND DRAFTING: DAVID EDWARDS.



NE CORNER SECTION 36
18" CEDAR S.21 1/4°W., 132.0'
20" CEDAR SNAG N.85°W., 87.8'
SET 6 FOOT STEEL POST 2' SOUTH

CORNER TO SECTIONS 30 & 31
15" CEDAR N.46 3/4°E., 42.9'
27" FIR SNAG S.38°E., 60.7'
SET 6 FOOT STEEL POST 2' NORTH

EAST 1/4 CORNER SECTION 36
12" CEDAR S.57 1/4°W., 10.6'
12" CEDAR N.22 1/4°W., 25.7'
SET 6 FOOT STEEL POST 2' NORTH

ALL FOUND BEARING TREES HAVE HEALED
BLAZES

