

FILED

Date: 6/14/2010 By: JC

This survey consists of:

Map: _____

Narrative: _____

Corner F. No. 65/69-30

DOUGLAS COUNTY
SURVEYOR

CORNER REPORT FORM

Section 32 Township 23 South Range 6 West

Douglas County Date: 6/1/2010

Corner Designation Section Corner 31 32 6 5

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. See T 23 S, R 6 W, Card 200100

Monument (s) & Accessories Found: (Condition and Source)

BLM Brass Cap dated 1957 with the following Accessories;

30" Fir Bears N22°E, 35.0' open face

18" Hemlock Bears S63°E, 23.1' healed face blow down

17" Hemlock Bears S30°W, 11.2' rotted face

40" Fir bears N74°W, 37.6' healed face

13" Hemlock Bears S20°W, 20.6' healed face

Monument Detail

Sketch

T23S R6W
 S31 | S32
 S6 | S5
 T24S
 1957

Monument Set (Procedures and Description)

New Accessories

Location & Comments

Compass Declination: 17-1/2° E

Firm/Agency: Ward NorthWest Inc.

Address: P.O. Box 105, Florence, OR 97439

Party Chief: Ron Rice

Notes:

Witness: Josh Reed

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
ROBERT B. WARD JR
JULY 30 1970
1091

Renew 6/30/12

C.S. File No 65/69-30