FILED
Date: 6/14/2010 By: JC
This survey consists of:
Map: _____
Narrative: _____
Corner Rpt: CS 65/69-32
DOUGLAS COUNTY SURVEYOR

OREGON CORNER RESTORATION FORM

Section 1 Township 24 South, Range 7 West
County Douglas Date 1 June 2010

Corner Description
E 1/16 Corner
Section 1

___ Condition Report Only
___ Not Found
_X_ Renewed
___ Unrecorded
___ Surveyed In
___ Referenced Out

Previous Renewals / Surveys, etc.

Monument (s) & Accessories Found: (Condition and Source)
Found 3-1/4" BLM brass cap dated 1993 with the following accessories:
15" D. Fir bears S21°W 29.7' – healed face
13"D. Fir bears S82°E 48.8' – healed face
Wilford Haines "T- iron" bears S54°25'00"E 58.74' with BT in evidence

Monument Detail

Sketch

E1/16 S1
1993

Monument Set (Procedures and Description)
None

New Accessories
None

Location & Comments
Corner has steel post adjacent to it. All BT's have red painted bands and yellow tags.

Compass Declination 17° East
Firm/Agency Ward NorthWest Inc.
Address P.O. Box 105
Florence, OR 97439
Party Chief Ron Rice
Notes
Witness Josh Reed

Surveyor's Seal

REGISTERED PROFESSIONAL
LAND SURVEYOR
Ronald L. Rice
OREGON
JULY 9, 2002
RONALD L. RICE
54633LS

RENEWS: 12-31-2010

C.S. File No 65/69-32