

OREGON CORNER RESTORATION FORM

Section 36 Township 23 South, Range 7 West
County Douglas Date 1 June 2010

FILED
Date: 6/14/2010 By: JC
This survey consists of:
Map: _____
Narrative: _____
Corner Rpt: C.S. 65/69-33
DOUGLAS COUNTY
SURVEYOR

Corner Description

S 1/4 Corner
Section 36

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals / Surveys, etc.

Monument (s) & Accessories Found: (Condition and Source)

Found 3-1/4" BLM brass cap dated 1993 with the following accessories:
27" W. Fir bears N9°E 51.5' – healed face
18"D. Fir bears N34°W 44.2' – healed face
3-1/4" BLM brass cap marking S1/4 of section 1
bears N89°52'30"W 213.84'
3-1/4" BLM brass cap erroneously established
bears S7°38'30"W 30.69'

Monument Detail

Sketch

T23S R7W
1/4 S36

T24S R7W
1993

Monument Set (Procedures and Description)

None

New Accessories

None

Location & Comments

Corner has steel post Compass Declination 17° East
adjacent to it. Firm/Agency Ward NorthWest Inc.
All BT's have red painted
bands and yellow tags. Address P.O. Box 105
_____ Florence, OR 97439
_____ Party Chief Ron Rice
_____ Notes _____
_____ Witness Josh Reed

Surveyor's Seal



RENEWS: 12-31-2010

C.S. File No 65/69-33