

OREGON CORNER RESTORATION FORM

Section 8 Township 24 South, Range 6 West
County Douglas Date 8 July 2010

FILED
Date: 7/15/2010 By: JC

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: CS 65/69-43

DOUGLAS COUNTY
SURVEYOR

Corner Description

Southeast Corner

Section 8

___ Condition Report Only

___ Not Found

X Renewed

___ Unrecorded

___ Surveyed In

___ Referenced Out

Previous Renewals / Surveys, etc.

Monument (s) & Accessories Found: (Condition and Source)

Found 3-1/4" BLM brass cap dated 1963 with the following accessories:

30" Hemlock bears N35-1/2"E 16.2' - healed face

14" D. Fir bears S68"W 25.2' - healed face

11" D. Fir bears S18"W 24.3' - healed face

Monument Detail

Sketch

T24S R6W

S8 | S9

S17 | S16

1963

Monument Set (Procedures and Description)

None

New Accessories

14" D. Fir bears S85"E 45.6' - blazed, scribed "T24S R6W S16 BT"

Location & Comments

Corner has steel post _____ Compass Declination 17' East

adjacent to it _____ Firm/Agency Ward NorthWest Inc.

All BT's have red painted _____



bands and yellow tags. _____ Address P.O. Box 105
_____ Florence, OR, 97439

_____ Party Chief Ron Rice

_____ Notes _____

_____ Witness Josh Reed

Surveyor's Seal



OREGON
JULY 9, 2002
RONALD L. RICE
54633LS

RENEWS: 12-31-2010

C.S. File No 65/69-43