

OREGON CORNER RESTORATION FORM

FILED

Date: 7/15/2010 By: X

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: CS 65/69-44

Section 12 Township 24 South, Range 7 West
County Douglas Date 8 July 2010

Corner Description

Southeast Corner

Section 12

Condition Report Only **DOUGLAS COUNTY SURVEYOR**

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

Previous Renewals / Surveys, etc.

Monument (s) & Accessories Found: (Condition and Source)

Found 3-1/4" BLM brass cap dated 1993 with the following accessories:

30" W. Fir bears N85°E 18.5' – healed face

30" Madrone bears N73°W 19.8' – healed face

25" W. Fir bears S74°E 59.4' – healed face

17" D. Fir bears S24°W 9.2' – healed face

Monument Detail

Sketch

T24S

R7W R6W

S12 | S7

S13 | S18

1993

Monument Set: (Procedures and Description)

None

New Accessories

None

Location & Comments

Corner has steel post _____ Compass Declination 17° East

adjacent to it. _____ Firm/Agency Ward NorthWest Inc.

All BT's have red painted _____

bands and yellow tags. _____ Address P.O. Box 105


_____ Florence, OR 97439

_____ Party Chief Ron Rice

_____ Notes _____

_____ Witness Josh Reed

Surveyor's Seal



RENEWAL: 12-31-2010

C.S. File No 65/69-44