

OREGON CORNER RESTORATION FORM

FILED
Date: 7/15/2010 By: JC
This survey consists of:

Section 12 Township 24 South, Range 7 West
County Douglas Date 8 July 2010

Map: _____
Narrative: _____
Corner Rpt: CS 65/69-45

Corner Description

South 1/4 Corner
Section 12

DOUGLAS COUNTY
SURVEYOR
 Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewals / Surveys, etc.

Monument (s) & Accessories Found: (Condition and Source)

Found 3-1/4" BLM brass cap dated 1994 with the following accessories:
23" D. Fir bears S22°E 12.5' - healed face
11" D. Fir bears N45°W 4 0' - healed face
5/8" Rebar per CSF M33-8 bears S88°42'50"E 166.27' (record 164.24')

Monument Detail

Sketch
T24S R7W
1/4 S12
S13
1994

Monument Set (Procedures and Description)

None


New Accessories

18" D. Fir bears S17°W 8.3' - blazed, scribed "1/4 S13 BT"

Location & Comments

Corner has steel post _____ Compass Declination 17° East
adjacent to it _____ Firm/Agency Ward NorthWest Inc.
All BT's have red painted _____
bands and yellow tags. _____ Address P.O. Box 105
_____ Florence, OR 97436
_____ Party Chief Ron Rice
_____ Notes _____
_____ Witness Josh Reed

Surveyor's Seal



RENEWS: 12-31-2010

C.S. File No 65/69-45