

FILED

Date: 8-3-2010 By: JC

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: 65/69-47

DOUGLAS COUNTY
SURVEYOR

OREGON CORNER RESTORATION FORM

Section 22 Township 24 South, Range 7 West
County Douglas Date 30 July 2010

Corner Description

West 1/4 Corner
Section 22

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals / Surveys, etc.

Monument (s) & Accessories Found: (Condition and Source)

Found 1" plastic cap marked "ARTMAN RLS 2268" on 5/8" rebar with the following accessories:

- 13" D. Fir bears S8-1/2°E 56.3' – healed face
- 10" Maple bears N23-1/2°W 42.3' (record Myrtle bearing N20°W 43.6') – scribing visible
- 18" D. Fir stump bears N24°E 23.5' – healed face
- Record 40" Maple bearing S60°W 3.1' – down and removed
- 5/8" rebar with 1" plastic cap marked "ARTMAN RLS 2268" bears N0°39'50"E 144.53' (record N0°53'23"E 144.97')

Monument Detail

Sketch

ARTMAN
RLS 2268

Monument Set (Procedures and Description)

None

New Accessories

None

Location & Comments

Corner has steel post adjacent to it. Compass Declination 16° East
All BT's have red painted bands and yellow tags. Firm/Agency Ward NorthWest Inc.
 Address P.O. Box 105
Florence, OR 97439
 Party Chief Ron Rice
 Notes _____
 Witness Josh Reed

Surveyor's Seal



RENEWS: 12-31-2010

C.S. File No 65/69-47