FILED
Date: 8-3-2010 By: JC
This survey consists of:
Map:
Narrative:
Corner Rpt: 65/69-48
DOUGLAS COUNTY SURVEYOR

OREGON CORNER RESTORATION FORM

Section 22 Township 24 South, Range 7 West
County Douglas Date 30 July 2010

Corner Description
Southwest Corner
Section 22

X Condition Report Only
___ Not Found
___ Renewed
___ Unrecorded
___ Surveyed In
___ Referenced Out

Previous Renewals / Surveys, etc.

Monument (s) & Accessories Found: (Condition and Source)

Found 2-1/2" Douglas County brass cap dated 1957 with the following accessories:
21" D. Fir bears N56°W 12.0' – healed face
16" D. Fir bears N85°E 53.2' – healed face
11" D. Fir bears N76°W 21.3' – healed face
9" D. Fir bears S60°E 34.9' – healed face
22" X 6' D. Fir stump bears S33°W 54.4' – bark scribing visible

Monument Detail

Sketch

County Surveyors Office
21 22
+
28 27
1957

Monument Set (Procedures and Description)
None

New Accessories
None

Location & Comments
Corner has steel post adjacent to it. All BT's have red painted bands and yellow tags.

Compass Declination 16° East
Firm/Agency Ward NorthWest Inc.
Address P.O. Box 105
Florence, OR 97439
Party Chief Ron Rice
Notes
Witness Josh Reed

Surveyor's Seal

REGISTERED PROFESSIONAL LAND SURVEYOR
Ronald L. Rice
OREGON
JULY 9, 2002
RONALD L. RICE
54633LS

RENEWS: 12-31-2010

C.S. File No 65/69-48