

OREGON CORNER RESTORATION FORM

Section 16, Township 23 South, Range 8 West, W. M.
County Douglas Date 28 September 2010

FILED
Date: 11/16/2010 By: JC
This survey consists of:
Map: _____
Narrative: _____
Corner Rpt: CS 65/69-52
DOUGLAS COUNTY
SURVEYOR

Corner Description

Section Corner Sections 16-17-20-21

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals / Surveys, etc.

Monument (s) & Accessories Found: (Condition and Source)

Found 2-1/2" Douglas County brass cap dated 1966 with the following accessories:
60" D. Fir stump bears S 24° W 21.8' – open rotted face
50" D. Fir stump bears N 18° W 52.1' - healed face
Rotted Hemlock stump of indeterminate diameter bears N 61° E 19.1' – no marks
Rotted Hemlock stump of indeterminate diameter bears S 59° W 14.9' – no marks

Monument Detail

Sketch
T23S R8W
S17 S16
+
S20 S21
1966

Monument Set (Procedures and Description)

None

New Accessories

17" D. Fir bears S 61° E 10.5' – blazed, scribed "T23S R8W S21 BT"
15" D. Fir bears S 55° W 15.7' – blazed, scribed "T23S R8W S20 BT"
13" D. Fir bears N 65° W 16.0' – blazed, scribed "T23S R8W S17 BT"
14" D. Fir bears N 23° E 22.4' – blazed, scribed "T23S R8W S16 BT"

Location & Comments

Corner has steel post _____ Compass Declination 16° East
adjacent to it. _____ Firm/Agency Ward NorthWest Inc.
All BT's have red painted _____
bands and yellow tags. Address P.O. Box 105
_____ Florence, OR 97439
_____ Party Chief Ron Rice
_____ Notes _____
_____ Witness Josh Reed

Surveyor's Seal



RENEWS: 12-31-2010

C.S. File No 65/69-52