FILED
Date: 11/16/2010 By: JC
This survey consists of:
Map: ____
Narrative: ____
Corner Rpt: CS 65/69-54
DOUGLAS COUNTY SURVEYOR

OREGON CORNER RESTORATION FORM

Section 12 Township 24 South, Range 8 West W. M.
County Douglas Date 21 September 2010

Corner Description
Section Corner
Sections 12-13

___ Condition Report Only
___ Not Found
_X_ Renewed
___ Unrecorded
___ Surveyed In
___ Referenced Out

Previous Renewals / Surveys, etc.

Monument (s) & Accessories Found: (Condition and Source)
Found 2-1/2" Douglas County Surveyor's Office brass cap dated 1960
with the following accessories:
39" W. Red cedar bears N70°E 5.3' – open, rotted face
36" W. Red cedar bears S24°W 84.3' – healed face
36" W. Red cedar bears N47°W 55.8' – healed face
38" rotted D. Fir stump bears N20°W 10.9' – rotted face

Monument Detail

Sketch

T24S
S12
R8W ---- R7W
S13
1960

Monument Set (Procedures and Description)
None

New Accessories
21" D. Fir bears S66°W 38.0' – blazed, scribed "T24S R8W S13 BT"

Location & Comments
Corner has steel post adjacent to it. All BT's have red painted bands and yellow tags.

Compass Declination 17° East
Firm/Agency Ward NorthWest Inc.
Address P.O. Box 105
Florence, OR 97439
Party Chief Ron Rice
Notes ____
Witness Josh Reed

Surveyor's Seal

REGISTERED PROFESSIONAL LAND SURVEYOR
Ronald L. Rice
OREGON
JULY 9, 2002
RONALD L. RICE
54633LS

RENEWS: 12-31-2010

C.S. File No 65/69-54