

FILED

Date: 11/16/2010 By: JC

This survey consists of: _____

Map: _____

Notation: _____

Corner Rpt: 65/69-55

DOUGLAS COUNTY
SURVEYOR

OREGON CORNER RESTORATION FORM

Section 12 Township 24 South, Range 8 West, W. M.
County Douglas Date 21 September 2010

Corner Description

1/4 Corner
Sections 12-13

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals / Surveys, etc.

Monument (s) & Accessories Found: (Condition and Source)

Found 3-1/4" BLM brass cap dated 1959 with the following accessories:

- 26" D. Fir bears N77-1/2°E 13.2' – healed face
- 29" Hemlock bears S60-1/2°W 10.6' – scribing visible
- 25" D. Fir bears S9°W 23.6' – healed face
- 24" D. Fir bears N5°E 5.0' – healed face
- 65" rotted D. Fir staub bears South 33.0' – rotted face

Monument Detail

Sketch
T24S R8W
S12
1/4 -----
S13
1959

Monument Set (Procedures and Description)

None

New Accessories

None

Location & Comments

Corner has steel post _____ Compass Declination 17° East
adjacent to it. _____ Firm/Agency Ward NorthWest Inc.
All BT's have red painted _____
bands and yellow tags. _____ Address P.O. Box 105
_____ Florence, OR 97439
_____ Party Chief Ron Rice
_____ Notes _____
_____ Witness Josh Reed

Surveyor's Seal



RENEWS: 12-31-2010

C.S. File No 65/69-55