

OREGON CORNER RESTORATION FORM

FILED
Date: 7/16 2010 By: X
This survey consists of:
Map: _____
Narrative: _____
Corner Rpt: CS 65/69-56
DOUGLAS COUNTY
SURVEYOR

Section 2, Township 25 South, Range 7 West, W. M.
County Douglas Date 21 September 2010

Corner Description

Section Corner Sections 2-3 &
34-35 T24S, R7W

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals / Surveys, etc.

Monument (s) & Accessories Found: (Condition and Source)

Found 2-1/2" BLM brass cap dated 1958 with the following accessories:
24" Cedar bears S 75-1/2° E 43.2' – scribing visible
40" D. Fir bears S 66° E 49.5' - bark scribing visible
40" D. Fir stump bears S 33-1/2° W 45.6' - bark scribing visible
22" Cedar bears N 45-1/2° E 35.6' – healed face
28" D. Fir bears N 71-1/2° W 51.2' – healed face
14" W. Fir bears S 71° E 2.0' – healed face
12" W. Fir (record Hemlock) bears S 78-1/2° W 45.6' – scribing visible

Monument Detail

Sketch
T24S R7W
S34 S35
+
S3 S2
T25S
1958

Monument Set (Procedures and Description)

None
New Accessories
None
Location & Comments

Corner has steel post adjacent to it. Compass Declination 16° East
All BT's have red painted bands and yellow tags. Firm/Agency Ward NorthWest Inc.
Address P.O. Box 105
Florence, OR 97439
Party Chief Robert Ward
Notes _____
Witness Josh Reed

Surveyor's Seal



RENEWS: 12-31-2010

C.S. File No 65/69-56