FILED
Date: 11/16/2010 By: JC
This survey consists of:
Map: ____
Narrative: ____
Corner Rpt: CS 65/69-58
DOUGLAS COUNTY SURVEYOR

OREGON CORNER RESTORATION FORM

Section 2, Township 25 South, Range 7 West, W.M.
County Douglas Date 21 September 2010

Corner Description

Section Corner Sections 2-3-10-11

___Condition Report Only

___ Not Found
_X_ Renewed
___ Unrecorded
___ Surveyed In
___ Referenced Out

Previous Renewals / Surveys, etc.

Monument (s) & Accessories Found: (Condition and Source)

Found 2-1/2" BLM brass cap dated 1958 with the following accessories:
17" D. Fir bears S 77° E 40.0' - bark scribing visible
22" W. Fir bears S 3° W 24.7' – healed face

Monument Detail

Sketch
T25S R7W
S3 S2
+
S10 S11
1958

Monument Set (Procedures and Description)
None

New Accessories
15" D. Fir bears N 21° W 9.2' – blazed, scribed "T25S R7W S3 BT"
15" D. Fir bears N 26° E 7.8' – blazed, scribed "T25S R7W S2 BT"

Location & Comments

Corner has steel post adjacent to it. All BT's have red painted bands and yellow tags.

Compass Declination 16° East
Firm/Agency Ward NorthWest Inc.
Address P.O. Box 105
Florence, OR 97439
Party Chief Ron Rice
Notes ____
Witness Josh Reed

Surveyor's Seal

REGISTERED PROFESSIONAL LAND SURVEYOR
Ronald L. Rice
OREGON
JULY 9, 2002
RONALD L. RICE
54633LS

RENEWS: 12-31-2010

C.S. File No 65/69-58