

FILED

Date: 3/21/2011 By: JC
This survey consists of:

Map: _____
Narrative: _____
Corner Rpt: CS 65/72-10

CORNER REPORT FORM

Section 18 Township 3/S Range 9W
Douglas County Date 3-11

CORNER DESIGNATION

140500

Condition Report only
Not Found
Renewed
Unrecorded
Surveyed In
Referenced out

Previous Renewals/Surveys, etc:

Lecklider M 23-68 6/62
Johnstone LS 498 7/78

Monument(s) & Accessories Found: (Condition and Source)

Fd. $\frac{5}{8}$ " I. ROD
44" FIR S43°W 14 $\frac{2}{3}$ Feet Vis. Scribes
30" D. FIR STUMP N12E 14 $\frac{1}{2}$ FT (TIN ON TOP)

Monument Detail

Sketch

$\frac{5}{8}$ " I. ROD

Monument Set (Procedures and Description)

None

New Accessories

12" D. FIR N48°E 13 $\frac{1}{2}$ FT scribed $\frac{1}{4}$ S7 BT
50" Cedar S39°E 23 $\frac{3}{4}$ FT scribed $\frac{1}{4}$ S10 BT

Location & Comments

CORNER IS APPROX
400' EAST OF MAIN
N-S RIDGE & ROAD
ON GENTLE NORTH
SLOPE

Compass Declination

Firm/Agency: i.e. Engineering, Inc.

Address: 505 SE Main
Roseburg, OR 97470

Party Chief: Palmer

Notes:

Witness:

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Ronald A. Quimby
OREGON
JULY 14, 1978
RONALD A. QUIMBY
1654

EXP 12-31-12

C.S. File No 65/72-10