


USDA-FOREST SERVICE

Index


CORNER RECORD (SEARCH)

File No. R-3 PROJ. NO. \_\_\_\_\_ CORNER 1/4  
 TOWNS. 27S RANGE 1W R.D. Glide COUNTY Douglas GCDB# 140300  
 MERID. WM FOREST UMPQUA STATE OR

<b>CORNER DIAGRAM</b> N ↑ 	<b>DESCRIBE CORNER MONUMENT FOUND</b> Found 1" Iron Pipe with 2-1/2" County Surveyors Office Brass Cap Projecting 14" above mound of stone, cap marked "T27S R1W S19 1/4 S30 1969" "County Surveyors Office"																								
	<b>DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND</b> <table border="1"> <thead> <tr> <th>DIA</th> <th>TYPE</th> <th>BEARS</th> <th>DIST</th> <th>FACE/MARKINGS</th> </tr> </thead> <tbody> <tr> <td>30"</td> <td>Cedar Snag</td> <td>N 17 E</td> <td>49.0 FT.</td> <td>Scribing Visb. On Part. Healed Double Blz</td> </tr> <tr> <td></td> <td>Root Hole</td> <td>S 48 E</td> <td>22.3 FT.</td> <td>Rotted remains Cedar found down the hill</td> </tr> <tr> <td>32"</td> <td>Fir Stump</td> <td>S 32 E</td> <td>56 FT.</td> <td>Scribing Visb. On Part. Healed Double Blz</td> </tr> <tr> <td>21"</td> <td>Cedar Stump</td> <td>S 30 W</td> <td>41.6 FT.</td> <td>"1/4S30BT" Visb. On Open Double Blaze</td> </tr> </tbody> </table>	DIA	TYPE	BEARS	DIST	FACE/MARKINGS	30"	Cedar Snag	N 17 E	49.0 FT.	Scribing Visb. On Part. Healed Double Blz		Root Hole	S 48 E	22.3 FT.	Rotted remains Cedar found down the hill	32"	Fir Stump	S 32 E	56 FT.	Scribing Visb. On Part. Healed Double Blz	21"	Cedar Stump	S 30 W	41.6 FT.
DIA	TYPE	BEARS	DIST	FACE/MARKINGS																					
30"	Cedar Snag	N 17 E	49.0 FT.	Scribing Visb. On Part. Healed Double Blz																					
	Root Hole	S 48 E	22.3 FT.	Rotted remains Cedar found down the hill																					
32"	Fir Stump	S 32 E	56 FT.	Scribing Visb. On Part. Healed Double Blz																					
21"	Cedar Stump	S 30 W	41.6 FT.	"1/4S30BT" Visb. On Open Double Blaze																					
<b>PHOTO IDENTIFICATION DATA</b> Photo No. <u>None</u> Filed At. <u>None</u> Obj. Ident. <u>None</u> Ident. By <u>None</u> Signature _____	<b>DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER</b> Corner is on west slope in timber approx. 500' above white creek Take 2792 road to 150 spur heading west, follow to end and continue west to small draw, follow draw NW to corner ~500' from creek																								
<b>PLANE COORDINATE POSITION DATA</b> State <u>OR</u> Zone <u>UTM-10M</u> North <u>4782826</u> East <u>511012.4</u> Estab. By <u>GCDB</u>																									

Signature \_\_\_\_\_ Title \_\_\_\_\_ Division LANDS Headquarters SPRINGFIELD Date 7100-52 (3/68)  
 1/17/2011

CORNER RECORD (PERPETUATION)

<b>MONUMENT : DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT</b>	REGISTERED PROFESSIONAL LAND SURVEYOR  OREGON JULY 21, 1992 JOHN C. RANSOM 2561
<b>ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE</b> Painted BT's red with 6" wide band at head height, painted face blaze, new nails on tags. Added 2 New Trees: 7" Fir Bears N 19° 18' E 10.43 FT. Scribed "1/4S19" "BT" on Double Blaze 10.14' to washer 7" Fir Bears S 54° 33' E 13.75 FT. Scribed "1/4S30" "BT" on Double Blaze 13.4' to washer All new trees include a 3/4" brass washer nailed between B and T on lower blaze, Washer stamped "LS2561"	
DONE BY: <u>Jonathan Drew</u> TITLE <u>LSIT</u> DATE <u>1/17/2011</u> PLS NO./AGENCY/STATE <u>LSIT-Maine</u> Certified Cor. Record Prepared ? _____ Filed At: _____ DATE _____	
<b>REMARKS</b>	

Index File No R-3 T. 27S R. 1W M. WM Proj No. \_\_\_\_\_ 0 Cor. 1/4

John Ransom  
 Boundary Lead  
 Siuslaw, Willamette, Umpqua, and Rogue River-Siskiyou National Forests  
 3106 Pierce Parkway  
 Springfield, OR 97477  
 Ph 541-225-6446  
 Email: jransom@fs.fed.us

FILED  
 Date: 4-6-2011 By: JC  
 This survey consists of:  
 Map \_\_\_\_\_  
 Narrative \_\_\_\_\_  
 Corner Pts. CS 65/72-15

DOUGLAS COUNTY  
 SURVEYOR  
 C.S. File No 65/72-15