

USDA-FOREST SERVICE

Index

CORNER RECORD (SEARCH)

File No. M-22 PROJ. NO. Little River CORNER SW 1/16
 TOWNS. 27S RANGE 2W R.D. Glide COUNTY Douglas GCDB# 620320
 MERID. W.M. FOREST Umpqua STATE Oregon

<p>CORNER DIAGRAM</p> <p>N ↑</p> <p>S 24</p>	<p>DESCRIBE CORNER MONUMENT FOUND</p> <p>Found 3" Brass Cap on 2" Galvanized Iron Pipe, flush with mound of stone</p> <p>Cap Marked: "T27S R2W SW1/16 S13 1977 LS 1005"</p> <p>DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND</p> <table border="1" style="width:100%; border-collapse: collapse;"> <thead> <tr> <th>DIA</th> <th>TYPE</th> <th>BEARS</th> <th>DIST</th> <th>FACE/MARKINGS</th> </tr> </thead> <tbody> <tr> <td>33"</td> <td>Cedar</td> <td>N 20° W</td> <td>128.0 FT</td> <td>Healed Double Blaze</td> </tr> <tr> <td>48"</td> <td>Cedar</td> <td>S 76° W</td> <td>136.7 FT</td> <td>Healed Double Blaze</td> </tr> </tbody> </table>	DIA	TYPE	BEARS	DIST	FACE/MARKINGS	33"	Cedar	N 20° W	128.0 FT	Healed Double Blaze	48"	Cedar	S 76° W	136.7 FT	Healed Double Blaze
DIA	TYPE	BEARS	DIST	FACE/MARKINGS												
33"	Cedar	N 20° W	128.0 FT	Healed Double Blaze												
48"	Cedar	S 76° W	136.7 FT	Healed Double Blaze												
<p>PHOTO IDENTIFICATION DATA</p> <p>Photo No. <u>None</u></p> <p>Filed At. <u>None</u></p> <p>Obj. Ident. <u>None</u></p> <p>Ident. By <u>None</u></p> <p style="text-align: center;">Signature</p>	<p>DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER</p> <p>Take Forest road 2701 to the 120 spur, follow 2701-120 north to 110 spur, Follow 110 spur to 020 spur, follow 020 spur south-east to turnout .25 mi past 170 spur heading east. From turnout walk Northwest about 75 ft to W1/16 corner, follow posted/blazed line North .25 miles to corner on steep northerly slope</p>															
<p>PLANE COORDINATE POSITION DATA</p> <p>State <u>OR</u> Zone <u>UTM-10M</u></p> <p>North <u>4784809</u></p> <p>East <u>509144</u></p> <p>Estab. By <u>GCDB</u></p> <p style="text-align: center;">Signature</p>	<table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td>Title</td> <td>Division</td> <td>Hedquarters</td> <td>Date</td> <td>7100-52 (3/68)</td> </tr> <tr> <td>LSIT</td> <td>LANDS</td> <td>SPRINGFIELD</td> <td>11/2010</td> <td></td> </tr> </table>	Title	Division	Hedquarters	Date	7100-52 (3/68)	LSIT	LANDS	SPRINGFIELD	11/2010						
Title	Division	Hedquarters	Date	7100-52 (3/68)												
LSIT	LANDS	SPRINGFIELD	11/2010													

CORNER RECORD (PERPETUATION)

<p>MONUMENT : DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT</p>	<p>REGISTERED PROFESSIONAL LAND SURVEYOR</p> <p><i>John Ransom</i></p> <p>OREGON JULY 31, 1992 JOHN C. RANSOM 2561</p>
------------------------------------------------------------------------------------------------	--------------------------------------------------------------------------------------------------------------------------------------------

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Painted 6" Band around BT's and painted face blazes, new nails on signs, cleared brush around corner

Marked new tree:

9" Fir BRS N 72° W 6.82 FT Scribed "SW 1/16 S13""BT" on double blaze

New tree measured with Staff Compass(15°45' DEC) and tape

DONE BY: Jonathan Drew TITLE LSIT DATE 11/2010 PLS NO./AGENCY/STATE USDA Forest Service

Certified Cor. Record Prepared? _____ Filed At: _____ DATE _____

REMARKS

Found Steel Post approx 2.5 FT from corner
Line maintained South .25 Miles

Index File No M-22 T. 27S R. 2W M. W.M. Proj No. Little River Cor. SW 1/16

John Ransom
Boundary Lead
Siuslaw, Willamette, Umpqua, and Rogue River-Siskiyou National Forests
3106 Pierce Parkway
Springfield, OR 97477
Ph 541-225-6446
Email: jransom@fs.fed.us

FILED

Date: 4-6-2011 By: JC
This survey consists of:
Map: _____
Narrative: _____
Corner Rep: CS 65/72-20

DOUGLAS COUNTY
SURVEYOR

C.S. File No 65/72-20