

USDA-FOREST SERVICE

Index **CORNER RECORD (SEARCH)**
 File No. G-3 PROJ. NO. Little River CORNER C 1/4
 TOWNS. 28S RANGE 2W R.D. Glide COUNTY Douglas GCDB# 140540
 MERID. W.M. FOREST Umpqua STATE Oregon

CORNER DIAGRAM 	DESCRIBE CORNER MONUMENT FOUND Found 2-1/2" Aluminum Cap on 1" Iron Pipe, Projecting 14" above rocky ground, Cap Marked "T28S R2W C1/4 S7 RE 4287" "DO NOT DISTURB"																								
	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND <table border="1"> <thead> <tr> <th>DIA</th> <th>TYPE</th> <th>BEARS</th> <th>DIST</th> <th>FACE/MARKINGS</th> </tr> </thead> <tbody> <tr> <td>30"</td> <td>Fir Stump</td> <td>S 46° E</td> <td>23.2 FT</td> <td>Rotten Fragmented scribe visable on part. Healed Double Blaze</td> </tr> <tr> <td>30"</td> <td>Fir Stump</td> <td>N 52° W</td> <td>27.1 FT</td> <td>"4S7""BT" visable scribe on Part. Healed Double Blaze</td> </tr> <tr> <td>7"</td> <td>Live Oak</td> <td>N 4° W</td> <td>13.4 FT</td> <td>Healed Double Blaze, alive but 1/2 rotted</td> </tr> <tr> <td>21"</td> <td>Fir</td> <td>N 80° E</td> <td>20.0 FT</td> <td>Healed Double Blaze</td> </tr> </tbody> </table>	DIA	TYPE	BEARS	DIST	FACE/MARKINGS	30"	Fir Stump	S 46° E	23.2 FT	Rotten Fragmented scribe visable on part. Healed Double Blaze	30"	Fir Stump	N 52° W	27.1 FT	"4S7""BT" visable scribe on Part. Healed Double Blaze	7"	Live Oak	N 4° W	13.4 FT	Healed Double Blaze, alive but 1/2 rotted	21"	Fir	N 80° E	20.0 FT
DIA	TYPE	BEARS	DIST	FACE/MARKINGS																					
30"	Fir Stump	S 46° E	23.2 FT	Rotten Fragmented scribe visable on part. Healed Double Blaze																					
30"	Fir Stump	N 52° W	27.1 FT	"4S7""BT" visable scribe on Part. Healed Double Blaze																					
7"	Live Oak	N 4° W	13.4 FT	Healed Double Blaze, alive but 1/2 rotted																					
21"	Fir	N 80° E	20.0 FT	Healed Double Blaze																					
PHOTO IDENTIFICATION DATA Photo No. <u>None</u> Filed At. <u>None</u> Obj. Ident. <u>None</u> Ident. By <u>None</u> Signature _____	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER Corner falls on steep South slope, access from forest road 25. Take 25 to 4x4 Post on south side of road. Follow posted blazed line south ~150 FT. to corner																								
PLANE COORDINATE POSTION DATA State <u>OR</u> Zone <u>UTM-10M</u> North <u>4777383</u> East <u>501456</u> Estab. By <u>GCDB</u>																									

Signature Title LSIT Division LANDS Headquarters SPRINGFIELD Date 11/2010 7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT : DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT _____	REGISTERED PROFESSIONAL LAND SURVEYOR OREGON JULY 21, 1992 JOHN C. RANSOM 2561
ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE Painted 6" Band around BT's and painted face blazes, new nails on signs, cleared brush around corner Marked new tree 10" Fir BRS N 11° E 13.58 FT Scribed "C1/4 S7" "BT" on double blaze New tree measured with staff compass(15.75°DEC)/ tape	
DONE BY: <u>Jonathan Drew</u> TITLE <u>LSIT</u> DATE <u>11/2010</u> PLS NO./AGENCY/STATE <u>USDA Forest Service</u> Certified Cor. Record Prepared ? _____ Filed At: _____ DATE _____	
REMARKS Drove Aluminum post North 3.5 FT and East .9 FT, each with property boundary and land survey monument signs. Line Maintained to North .5 Miles	

Index File No G-3 T. 28S R. 2W M. W.M. Proj No. Little River Cor. C 1/4

John Ransom
 Boundary Lead
 Siuslaw, Willamette, Umpqua, and Rogue River-Siskiyou National Forests
 3106 Pierce Parkway
 Springfield, OR 97477
 Ph 541-225-6446
 Email: jransom@fs.fed.us

FILED
 Date: 4-6-2011 By: JC
 This survey consists of:
 Map: _____
 Narrative: _____
 Corner Rpt: CS 65/72-22

DOUGLAS COUNTY SURVEYOR
 C.S. File No 65/72-22