

**REWITNESSED CORNER FOR  
STATE OF OREGON – DEPARTMENT OF FORESTRY**

Southwest corner for Section 31, Township 22 South, Range 10 West, W.M., Coos and Douglas Counties, Oregon.

**ORIGINAL by Aurelius Todd, 1894, Contract No. 629**

20" x 12" x 8" stone (in place, no marks visible) from which a:

- 36" Fir N73°E 44 lks.; now 44" x 3 ft. high rotted stump in place, face rotted.
- 30" Fir S24°W 12 lks.; now 12" x 2 ft. high rotted stub in place, no marks visible.
- 40" Fir N55°W 29 lks.; missing.

**RESTORATION by Arnold G. Gibson, 1971**

Oregon State Board of Forestry 1 ½" x 36" galvanized iron pipe with 3" bronze cap from which a:

- 22" Fir N42°E 10.60 ft.; now 23" in place, face closed, added bearing tree tag.
- 33" Fir N09°W 10.60 ft.; now 42" N09°E, face closed, with yellow metal location poster.
- 4" x 4" x 72" White Painted Cedar Post S01°W 2.7 ft.; missing

**REWITNESSED from the above pipe and cap:**

- Carsonite witness post N71°W 2.60 ft. to base.
- Carsonite witness post S20°E 2.10 ft. to base.

Magnetic variation set at 19° East.

Dated June 13, 2011

Rewitnessed by Tim VanVleet under my direction.  
Tim VanVleet

**FILED**

Date: 7-25-2011 By: JC  
This survey consists of:  
Map: \_\_\_\_\_  
Narrative: \_\_\_\_\_  
Corner Rpt: CS 65/72-30

**DOUGLAS COUNTY  
SURVEYOR**

Rewitnessed By:

**REGISTERED  
PROFESSIONAL  
LAND SURVEYOR**

*James M. McIntosh*

**OREGON  
JULY 13, 1984  
JAMES M. MCINTOSH  
2103**

James M. McIntosh  
63612 Fifth Road  
Coos Bay, Oregon

Expiration date of certificate 12-31-12

Present and witnessed by Ralph C. Hall

**C.S. File No** 65/72-30