

OREGON CORNER RESTORATION FORM

Section 36 Township 21 South, Range 9 West
County Douglas Date 1 December 2011

FILED
Date: 12/21/2011 By: JC
This survey consists of:
Map: _____
Narrative: _____
Corner Rpt: CS 65/72-47

**DOUGLAS COUNTY
SURVEYOR**

Corner Description

East 1/4 Corner

___ Condition Report Only

- ___ Not Found
- X Renewed
- ___ Unrecorded
- ___ Surveyed In
- ___ Referenced Out

Previous Renewals / Surveys, etc.

Monument (s) & Accessories Found: (Condition and Source)

Found 2-1/2" GLO brass cap dated 1945 with the following accessories:

None were recovered

Monument Detail

Sketch

1/4
S36 | S31
1945

Monument Set (Procedures and Description)

Corner was referenced and removed to protect it from logging, then reset after logging based on my references. Corner is located in recent clear cut with limited accessories.

New Accessories

- 32" D. Fir stump bears N41°E 17.66' to head of 60D nail in center of face
- 31" D. Fir stump bears N54°W 25.70' to head of 60D nail in center of face
- 35" D. Fir bears S26°E 144.3' – blazed, scribed "1/4 S31 BT"

Location & Comments

Corner has steel post adjacent to it. Compass Declination 16° east
All BT's have red painted bands and yellow tags. Firm/Agency Ward NorthWest Inc.
 Address 1732 Laurel Pl. Ste. A
Florence, OR 97439
 Party Chief Ron Rice
 Notes _____
 Witness Matt Bliss

Surveyor's Seal



RENEWS: 12-31-2012

C.S. File No 65/72-47