FILED
Date: 2-17-2012 By: JC
This survey consists of:
Map: ____
Narrative: ____
Corner Rpt: 65/76-14
DOUGLAS COUNTY
SURVEYOR

OREGON CORNER RESTORATION FORM

Section 26 Township 20 South, Range 8 West
County Douglas Date 13 February 2012

Corner Description
1/4 Corner
Sections 26, 35

___ Condition Report Only
___ Not Found
_X_ Renewed
___ Unrecorded
___ Surveyed In
___ Referenced Out

Previous Renewals / Surveys, etc.

Monument (s) & Accessories Found: (Condition and Source)
Found BLM brass cap dated 1950 with the following accessories:
40" Rotted D. Fir stump bears S83-1/4°E 29.0' – rotted face
20" Rotted D. Fir stump bears N17-1/2°E 33.0' – scribing visible

Monument Detail

Sketch

Monument Set (Procedures and Description)
None

New Accessories
15" D. Fir bears N3°W 11.0' – blazed, scribed "1/4 S26 BT"
19" D. Fir bears S6°W 10.9' – blazed, scribed "1/4 S35 BT"
16" D. Fir bears S67°W 17.6' – blazed, scribed "1/4 S35 BT"
17" D. Fir bears N72°E 37.7' – blazed, scribed "1/4 S26 BT"

Location & Comments
Corner has steel post adjacent to it. All BT's have red painted bands and yellow tags.

Compass Declination 16° East
Firm/Agency Ward NorthWest Inc.
Address 1732 Laurel Pl. Ste. A
Florence, OR 97439
Party Chief Ron Rice
Notes
Witness Jason Collver

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR
Ronald L. Rice
OREGON
JULY 9, 2002
RONALD L. RICE
54633LS

RENEWS: 12-31-2012

C.S. File No 65/76-14