

OREGON CORNER RESTORATION FORM

Section 26 Township 20 South, Range 8 West  
County Douglas Date 13 February 2012

FILED  
Date: 2-17-2012 By: Jc  
This survey consists of:  
Map: \_\_\_\_\_  
Narrative: \_\_\_\_\_  
Corner Rpt: CS 65/7b-15

DOUGLAS COUNTY  
SURVEYOR

Corner Description

1/4 Corner  
Sections 23, 26

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals / Surveys, etc.

Monument (s) & Accessories Found: (Condition and Source)

Found BLM brass cap dated 1950 with the following accessories:  
12" D. Fir stump bears N76-1/4°W 22.4' – scribing visible  
22" Rotted Hemlock stump bears S13-1/2°E 20.5' – rotted face

Monument Detail

Sketch

Monument Set (Procedures and Description)

None

New Accessories

15" D. Fir bears S41°W 17.3' – blazed, scribed "1/4 S26 BT"  
15" D. Fir bears S29°E 17.8' – blazed, scribed "1/4 S26 BT"  
14" D. Fir bears N4°W 8.6' – blazed, scribed "1/4 S23 BT"  
10" D. Fir bears N79°W 8.6' – blazed, scribed "1/4 S23 BT"

Location & Comments

Corner has steel post adjacent to it. Compass Declination 16° East  
All BT's have red painted bands and yellow tags. Firm/Agency Ward NorthWest Inc.  
Address 1732 Laurel Pl. Ste. A  
Florence, OR 97439  
Party Chief Ron Rice  
Notes \_\_\_\_\_  
Witness Jason Collver

Surveyor's Seal



RENEWS: 12-31-2012

C.S. File No 6576-15