

OREGON CORNER RESTORATION FORM

FILED

Date: 2/17/2012 By: JC

This survey consists of:

Section 24 Township 20 South, Range 8 West

County Douglas

Date 13 February 2012

Map: _____

Narrative: _____

Corner Rpt: CS 65/76-18

DOUGLAS COUNTY
SURVEYOR

Corner Description

1/4 Corner

Sections 24, 25

Condition Report Only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

Previous Renewals / Surveys, etc.

Monument (s) & Accessories Found: (Condition and Source)

Found BLM brass cap dated 1950 with the following accessories:

16" D. Fir bears S44-3/4°E 16.1' – healed face

10" D. Fir bears N71-3/4°W 8.6' – healed face

40" Rotted Hemlock stump bears N36°W 39.6' – rotted face

22" Hemlock snag bears S9°W 17.2' – no marks visible

Monument Detail

Sketch

Monument Set (Procedures and Description)

None

New Accessories

14" D. Fir bears S46°W 38.9' – blazed, scribed "1/4 S25 BT"

12" D. Fir bears N90°E 15.6' – blazed, scribed "1/4 S24 BT"

Location & Comments

Corner has steel post adjacent to it.

Compass Declination 16° East

All BT's have red painted

bands and yellow tags.

Firm/Agency Ward NorthWest Inc.

Address 1732 laurel Pl. Ste. A

Florence, OR 97439

Party Chief Ron Rice

Notes _____

Witness Jason Collver

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Ronald L. Rice

OREGON
JULY 9, 2002
RONALD L. RICE
54633LS

RENEWS: 12-31-2012

C.S. File No 65/76-18