

FILED

Date: 2-17-2012 By: JC

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: CS 65/76-19

DOUGLAS COUNTY
SURVEYOR

OREGON CORNER RESTORATION FORM

Section 24 Township 20 South, Range 8 West
County Douglas Date 13 February 2012

Corner Description

Section Corner
Sections 24, 25 Only

Condition Report Only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

Previous Renewals / Surveys, etc.

Monument (s) & Accessories Found: (Condition and Source)

Found BLM brass cap dated 1950 with the following accessories:

12" D. Fir bears S71-3/4°W 39.7' – healed face

15" D. Fir bears N13-1/4°W 11.1' – healed face

41" Decayed D. Fir stump bears S71°W 55.4' – no marks visible

27" Decayed D. Fir stump bears N47°W 46.9' – no marks visible

65" Decayed D. Fir stump bears N55°W 81.5' – no marks visible

Monument Detail

Sketch

Monument Set (Procedures and Description)

None

New Accessories

None

Location & Comments

Corner has steel post _____ Compass Declination 16° East
adjacent to it. _____ Firm/Agency Ward NorthWest Inc.

All BT's have red painted _____
bands and yellow tags. _____ Address 1732 Laurel Pl. Ste. A
_____ Florence, OR 97439

_____ Party Chief Ron Rice

_____ Notes _____

_____ Witness Jason Collver

Surveyor's Seal



RENEWS: 12-31-2012

C.S. File No 65/76-19