

CORNER REPORT FORM

Section 2 Township 30S Range 3W
Douglas County Date 2-2012

CORNER DESIGNATION

S.W. 1/16

Condition Report only
Not Found
Renewed
Unrecorded
Surveyed In
Referenced out

Previous Renewals/Surveys, etc:

M 86-6 M 17-51

Monument(s) & Accessories Found: (Condition and Source)

FD 5/8" BRASS ROD
A 2" CEDAR S 70° E 51.1 Feet GOOD SCORR
A 14" CEDAR STUB 6' LONG DOWN & ROTTED V/S SCRIBES

Monument Detail

Sketch

5/8" BRASS ROD 6" ABOVE GROUND

FILED

Date: 2/24/2012 By: JL

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: CS 65/76-25

DOUGLAS COUNTY
SURVEYOR

Monument Set (Procedures and Description)

New Accessories

A 12" D FIR S 69° W 13.6 FT
SCRIBED S.W. 1/16 52 FT
ON SINGLE FACE

Location & Comments

CORNER IS NEAR
TOP OF N-S RIDGE
ON EAST SIDE
APPROX. 50' EAST
OF ROAD.

Compass Declination

Firm/Agency: i.e. Engineering, Inc.

Address: 809 S.E. Pine Street
Roseburg, OR 97470

Party Chief: R. Quimby

Notes:

Witness:

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 14, 1978
RONALD A. QUIMBY
1654

C.S. File No 65/76-25 EXP 12-31-12