

FILED

Date: 3-12-2012 By: JC

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: CS 65/76-29

DOUGLAS COUNTY
SURVEYOR

OREGON CORNER RESTORATION FORM

Section 32 Township 23 South, Range 6 West
County Douglas Date 9 March 2012

Corner Description

Northwest Corner

Section 32

Condition Report Only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

Previous Renewals / Surveys, etc.

Monument (s) & Accessories Found: (Condition and Source)

Found 3-1/4" BLM brass cap dated 1994 with the following accessories:

22" D. Fir bears N 50-1/2° E 71.3' – healed face

17" D. Fir bears N 12-1/2° W 80.5' – healed face

13" D. Fir bears S 85-1/2° E 15.2' – healed face

19" D. Fir bears S 71° W 8.6' – healed face

Inverted BLM monument bears N 11° 04' 30" W 12.74' – flush to ground

Monument Detail

Sketch

Monument Set (Procedures and Description)

None

New Accessories

None

Location & Comments

Corner has steel post
adjacent to it.

All BT's have red painted
bands and yellow tags.

Compass Declination 17° East

Firm/Agency Ward NorthWest Inc.

Address 1732 Laurel Pl. Ste. A
Florence, OR 97439

Party Chief Ron Rice

Notes _____

Witness Jason Colliver

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Ronald L. Rice

OREGON
JULY 9, 2002
RONALD L. RICE
54633LS

RENEWS: 12-31-2012

C.S. File No 65/76-29