

FILED

Date: 3-21-2012 By: SC

This survey consists of:

Map: \_\_\_\_\_

Name: \_\_\_\_\_

Corner Rpt. CS 65/76-34

DOUGLAS COUNTY  
SURVEYOR

OREGON CORNER RESTORATION FORM

Section 14 Township 29 South, Range 9 West  
County Douglas Date 20 March 2012

Corner Description

Southwest Corner  
Section 14

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals / Surveys, etc.

Monument (s) & Accessories Found: (Condition and Source)

Found – DCSO 2½" brass cap on iron pipe, dated 1959. In fence corner wired to corner post.

Rotted Fir stump 12" dia., bears S.70°E., 25.1 ft. scribing visible

Rotted Fir stump 23" dia., bears N.65°W., 17.8 ft. scribing visible

D. Fir 20" dia., bears N.2°E., 10.9 ft., with healed blaze

I. Cedar 18" dia. snag bears S.47°E., 42.9 ft., scribing visible

Rotted Fir stump 18" dia., bears S.60°W., 26.4 ft., no marks

I. Cedar 27" dia., bears S.19°W., 19.8 ft., healed blaze

Monument Detail

Sketch

Monument Set (Procedures and Description)

None

New Accessories


14" D. Fir bears N 59° W 29.5 ft. blazed, scribed T29S R9W S15 BT

10" D. Fir bears S 54° E 10.0 ft. blazed, scribed T29S R9W S23 BT

Location & Comments

Corner has steel post Compass Declination 16° East  
adjacent to it. Firm/Agency Ward NorthWest Inc.  
All BT's have red painted  
bands and yellow tags. Address 1732 Laurel Pl. Ste. A  
 Florence, OR 97439  
 Party Chief Ron Rice  
 Notes \_\_\_\_\_  
 Witness Jason Collver

Surveyor's Seal



RENEWS: 12-31-2012

C.S. File No 65/76-34