

FILED

Date: 3-21-2012 By: JC

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: CS 65/76-35

OREGON CORNER RESTORATION FORM

Section 14 Township 29 South, Range 9 West

County Douglas

Date 20 March 2012

DOUGLAS COUNTY
SURVEYOR

Corner Description

S1/4

___ Condition Report Only

Section 14

- ___ Not Found
- Renewed
- ___ Unrecorded
- ___ Surveyed In
- ___ Referenced Out

Previous Renewals / Surveys, etc.

Monument (s) & Accessories Found: (Condition and Source)

Found – DCSO 2 1/2" brass cap on iron pipe, dated 1959, 1966, 1976. Set in fence line.

D. Fir, 22" dia., bears N.27°E., 47.9 ft., with healed double blazes.

W. Fir snag, 22" dia., bears N.25 3/4°E., 30.3 ft., with scribing visible

D. Fir, 10" dia., bears N.63°E., 13.6 ft., with healed blaze.

W. Fir stub, 13" dia. X 5 ft. tall, bears N.62 3/4°W., 17.0 ft., with scribing visible.

D. Fir, 6" dia., bears S.16 3/4°W., 11.6 ft., down

Monument Detail

Sketch

Monument Set (Procedures and Description)

None

New Accessories

14" W. Fir bears N 58° W 29.8 ft. blazed, scribed, 1/4 S14 BT

Location & Comments

Corner has steel post _____ Compass Declination 16° East
adjacent to it. _____ Firm/Agency Ward NorthWest Inc.

All BT's have red painted
bands and yellow tags. Address 1732 Laurel Pl. Ste. A
_____ Florence, OR 97439

_____ Party Chief Ron Rice

_____ Notes _____

_____ Witness Jason Colver

Surveyor's Seal



RENEWS: 12-31-2012

C.S. File No 65/76-35