

CORNER REPORT FORM

Section 34 Township 285 Range 8W
Douglas County Date 4/12

CORNER DESIGNATION

440100

Condition Report only
Not Found
Renewed
Unrecorded
Surveyed In
Referenced out

Previous Renewals/Surveys, etc:

M 37-25 DCSO 1997

Monument(s) & Accessories Found: (Condition and Source)

Fd DCSO BRASS CAP
Fd 28" D. FIR 564°E 64' FT Holed FACE
Fd 10' OAK 573E 5' FT
Fd 14" FIR N26°W 208 FT Vis scribes 1/4 534CS BT
Fd Down 24" FIR N 72° E 89' FT (SHAWY TAG)

Monument Detail

Sketch

Fd DCSO BRASS CAP

FILED
Date: 4/26/2012 By: SC
This survey consists of:
Map: _____
Narrative: _____
Corner Rpt: CS 65/76-41

Monument Set (Procedures and Description)

None

DOUGLAS COUNTY
SURVEYOR

New Accessories

A 10" D. FIR 589 W 67' FT scribed 5/4 BT.

Location & Comments

Surveyor's Seal

Compass Declination

Firm/Agency: i.e. Engineering, Inc.



Address: 809 SE Pine St.
Roseburg, OR 97470

Party Chief: J. LEONARD

Notes:

Witness: J. LAUB

C.S. File No 65/76-41



EXP 12-31-12