

OREGON CORNER RESTORATION FORM

FILED
Date: 5/2/2012 By: X
This survey consists of:
Map: _____
Narrative: _____
Corner Rpt: CS 65/76-46
DOUGLAS COUNTY
SURVEYOR

Section 36 Township 19 South, Range 9 West
County Douglas Date 1 May 2012

Corner Description

SW Corner
Section 36

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals / Surveys, etc.

Monument (s) & Accessories Found: (Condition and Source)

Found 2-1/2" G.L.O. brass cap on iron pipe, dated 1953
Alder 13" dia., bears N.4-1/2°E., 55 lks. dist. mkd. T19S R9W S36 BT.
(Missing)
Fir 43" dia., bears N.45°W., 73 lks. dist. mkd. T19S R9W S35 BT.
(Missing)

Monument Detail

Sketch

Monument Set (Procedures and Description)

None

New Accessories

24" D. Fir bears S 7° E 18.4 ft. blazed, scribed, T19S R9W S36 BT
21" D. Fir bears N 67° W 22.8 ft. blazed, scribed, T19S R9W S35 BT

Location & Comments

Corner has steel post adjacent to it. Compass Declination 16° East
All BT's have red painted bands and yellow tags. Firm/Agency Northwest Land Surveying Inc.
Address P.O. Box 2827 Florence, OR 97439
Party Chief Ron Rice
Notes _____
Witness Jason Collver

Surveyor's Seal



RENEWS: 12-31-2012

C.S. File No CS 65/76-46