

FILED

OREGON CORNER RESTORATION FORM

Date: 5-2-2012 By: X
This survey consists of:
Map: _____
Narrative: _____
Corner Rpt: CS 65/76-47

Section 36 Township 19 South, Range 9 West
County Douglas Date 1 May 2012

DOUGLAS COUNTY
SURVEYOR

Corner Description

NW Corner
Section 36

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals / Surveys, etc.

Monument (s) & Accessories Found: (Condition and Source)

Found 3-1/4" BLM brass cap on iron pipe, dated 1958

Hemlock snag, 18" dia., bears S.18°W., 81 lks., with scribe marks T19S R9W S35 BT visible on open blaze.

(No Evidence)

Hemlock, 38" dia., N.32-1/4°E., 65 lks., mkd: T19S R9W S25 BT.

(Found 41" dia. X 6' high stump with scribing visible. Metal capped)

Fir, 37" dia., bears S.36-3/4° W., 130 lks., mkd: T19S R9W S35 BT.

(Found 41" dia. X 7' high stump with rotted face)

Fir, 36" dia., bears N.32-1/2°W., 100 lks., mkd: T19S R9W S26 BT.

(Found 37" dia. X 6' high stump with healed face)

Monument Detail

Sketch

Monument Set (Procedures and Description)

None

New Accessories

13" D. Fir bears N 66° E 5.6 ft. blazed, scribed, T19S R9W S25 BT

13" D. Fir bears N 59° W 14.9 ft. blazed, scribed, T19S R9W S26 BT

15" D. Fir bears S 64° W 13.6 ft. blazed, scribed, T19S R9W S35 BT

Location & Comments

Corner has steel post _____ Compass Declination 16° East

adjacent to it. _____ Firm/Agency Northwest Land

All BT's have red painted _____ Surveying Inc.

bands and yellow tags. _____ Address P.O. Box 2827
_____ Florence, OR 97439

_____ Party Chief Ron Rice

_____ Notes _____

_____ Witness Jason Collver

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Ronald L. Rice

OREGON
JULY 9, 2002
RONALD L. RICE
54633LS

RENEWS: 12-31-2012

C.S. File No 65/76-47