FILED
Date: 5/2/2012 By: JC
This survey consists of:
Map: ____
Narrative ____
Corner Rpt: CS 65/76-51
DOUGLAS COUNTY SURVEYOR

OREGON CORNER RESTORATION FORM

Section 1 Township 20 South, Range 9 West
County Douglas Date 1 May 2012

Corner Description

N 1/4 Corner
Section 1 only

_X_ Condition Report
___ Not Found
___ Renewed
___ Unrecorded
___ Surveyed In
___ Referenced Out

Previous Renewals / Surveys, etc.

Monument (s) & Accessories Found: (Condition and Source)

Found 2-1/2" G.L.O. brass cap on iron pipe, dated 1953

22" Fir, stump bears S.55-1/2°E., 37.8', visible scribing.
(Found in same condition)
20" Fir, stump bears S.69°W., 27.4', healed face.
(Found in same condition)
17" Fir, bears S.22-1/2°W., 53.8', blazed & scribed "1/4 S1 BT"
(Found 21" Fir with healed face)
10" Fir, bears S.43-3/4°E., 15.6', blazed & scribed "1/4 S1 BT"
(Found 16" Fir with healed face)

Monument Detail Sketch

Monument Set (Procedures and Description)
None

New Accessories
None

Location & Comments

Corner has steel post adjacent to it. All BT's have red painted bands and yellow tags.

Compass Declination 16° East
Firm/Agency Northwest Land Surveying Inc.
Address P.O. Box 2827
Florence, OR 97439
Party Chief Ron Rice
Notes ____
Witness Jason Collver

Surveyor's Seal

REGISTERED PROFESSIONAL LAND SURVEYOR
Ronald L. Rice
OREGON JULY 9, 2002 RONALD L. RICE 54633LS

RENEWS: 12-31-2012

C.S. File No 65/76-51