

**REWITNESSED CORNER FOR
STATE OF OREGON – DEPARTMENT OF FORESTRY**

One quarter corner common to Sections 3 and 10, Township 23 South, Range 10 West, W.M., Douglas County, Oregon.

ORIGINAL by Levi Walker, 1906, Contract No. 763

X on face of sandstone bluff (in place) from which a:

- 6" Fir S21°E 14 lks.; missing.
- 6" Fir N73°W 28 lks.; now 26" x 1 ft. high rotted stump in place, exposed bottom of face, no marks visible.

REWITNESSED from original X on face of sandstone bluff:

- 7" Fir S89°E 4.4 ft. to aluminum nail in BT face scribed (1/4S10BT) Bearing tree tag.
- 8" Fir S10°E 15.2 ft. to aluminum nail in BT face scribed (1/4S10BT) Bearing tree tag.
- 6' Fir N39°W 16.2 ft. to aluminum nail in BT face scribed (1/4S3BT) Bearing tree tag.
- Carsonite Witness Post N70°W 16.6 ft. to base.

Magnetic variation set at 19° East.

Dated May 19, 2012

Rewitnessed by *Jim VanVleet* under my direction.
Tim VanVleet

Rewitnessed By:

REGISTERED
PROFESSIONAL
LAND SURVEYOR

James M. McIntosh

OREGON
JULY 13, 1984
JAMES M. MCINTOSH
2103

James M. McIntosh
63612 Fifth Road
Coos Bay, Oregon
Expiration date of certificate 12-31-2012

FILED

Date: 6-4-2012 By: JC
This survey consists of: _____
Map: _____
Name of _____
Corner: CS 65/76-57

**DOUGLAS COUNTY
SURVEYOR**

Present and witnessed by Ralph C. Hall

C.S. File No 65/76-57