

OREGON CORNER RESTORATION FORM

Section 6 Township 31 South, Range 9 West
County Douglas Date 8 June 2012

FILED

Date: 6-11-2012 By: JC

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: CS 65/76-60

DOUGLAS COUNTY
SURVEYOR

Corner Description

CN 1/16 Corner
Section 6

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals / Surveys, etc.

Monument (s) & Accessories Found: (Condition and Source)

Found 5/8" rebar (record 4" square post)

White Cedar, 9 inches, S 36 1/2° E, 24.6 feet, scribed "1/16 S6 BT"

(Found a 23" diam. White Cedar with healed face)

Red Cedar, 34 inches, S 89° W, 58.8 feet, scribed "1/16 S6 BT 473"

(Found 34" Red Cedar stump with no marks)

Monument Detail

Sketch

Monument Set (Procedures and Description)

None

New Accessories

10" D. Fir bears N 74° E 23.8 ft. blazed, scribed CN 1/16 S6 BT

Location & Comments

Corner has steel post _____ Compass Declination 16° East

adjacent to it. _____ Firm/Agency Northwest Land

All BT's have red painted _____ Surveying Inc.

bands and yellow tags. _____ Address P.O. Box 2827
_____ Florence, OR 97439

_____ Party Chief Ron Rice

_____ Notes _____

_____ Witness Jason Collver

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Ronald L. Rice

OREGON
JULY 9, 2002
RONALD L. RICE
54633LS

RENEWS: 12-31-2012

C.S. FILE 65/76-60