

OREGON CORNER RESTORATION FORM

Section 6 Township 31 South, Range 9 West  
County Douglas Date 8 June 2012

FILED  
Date: 6/11/2012 By: JC  
This survey consists of:  
Map: \_\_\_\_\_  
Narrative: \_\_\_\_\_  
Corner Rpt: CS 65/77-3

DOUGLAS COUNTY  
SURVEYOR

Corner Description

N 1/16 Corner  
Section 5 & 6

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals / Surveys, etc.  
C.S File # 51/265

Monument (s) & Accessories Found: (Condition and Source)

No monument found

Douglas Fir, 34 inches, N 6 1/2° E, 15.9 feet, scribed "1/16 S5 BT"  
(Found downed D. Fir, out of position)  
Douglas Fir, 30 inches, S 65° W, 13.0 feet, scribed " 1/16 S6 BT 473"  
(Found 30" diam. stump with scribing visible)

Monument Detail

Sketch

Monument Set (Procedures and Description)

Set 5/8" X 30" rebar with 2 1/2" aluminum cap – marked as shown  
Set by bearing – distance from remaining bearing tree per CS File# 51/265

N 1/16  
S6 ↓ S5  
2012  
54633 LS

New Accessories

8" D. Fir bears S 87° W 6.1 ft. blazed, scribed N 1/16 S6 BT  
8" D. Fir bears S 36° E 3.6 ft. blazed, scribed N 1/16 S5 BT

Location & Comments

Corner has steel post adjacent to it.  
All BT's have red painted bands and yellow tags.  
Compass Declination 16° East  
Firm/Agency Northwest Land Surveying Inc.  
Address P.O. Box 2827  
Florence, OR 97439  
Party Chief Ron Rice  
Notes \_\_\_\_\_  
Witness Jason Collver

Surveyor's Seal



RENEWS: 12-31-2012

C.S. FILE 65/77-3