

OREGON CORNER RESTORATION FORM

Section 5 Township 31 South, Range 9 West
County Douglas Date 8 June 2012

FILED
Date: 6/11/2012 By: JC
This survey consists of:
Map: _____
Narrative: _____
Corner Rpt: C.S. 65/77-4
DOUGLAS COUNTY
SURVEYOR

Corner Description

NE 1/16
Section 5

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals / Surveys, etc.
C.S. 55 / 23

Monument (s) & Accessories Found: (Condition and Source)

No monument found
56" D. Fir stump pulled out of position as logging tail-hold – scribing visible
44" D. Fir N 28 1/4° W 11.4' – healed face

Monument Detail

Sketch
NE1/16 S5
2012
54633LS

Monument Set (Procedures and Description)

Set 5/8" X 30" rebar with 2 1/2" aluminum cap – marked as shown
Set by bearing – distance from the remaining bearing tree, per record data C.S. 55 / 23

New Accessories

11" D. Fir bears S 47° E 19.0' – blazed, scribed NE 1/16 S5 BT

Location & Comments

Corner has steel post _____ Compass Declination 16° East
adjacent to it. _____ Firm/Agency Northwest Land
All BT's have red painted _____ Surveying Inc.
bands and yellow tags. _____ Address P.O. Box 2827
_____ Florence, OR 97439
_____ Party Chief Ron Rice
_____ Notes _____
_____ Witness Jason Collver

Surveyor's Seal



RENEWS: 12-31-2012

C.S. FILE 65/77-4