

CORNER REPORT FORM

Section 4 Township 3/S Range 4W
Douglas County Date 7-2012

CORNER DESIGNATION

500440

1/4 COR 14-15

Condition Report only
Not Found
Renewed
Unrecorded
Surveyed In
Referenced out

Previous Renewals/Surveys, etc:

MARKHAM 1959

Monument(s) & Accessories Found: (Condition and Source)

3/4" I. PIPE By MARKHAM
R 30" CEASE N48°W 41.5 FT GOOD SCAR
A DOWN 50" FIR WITH SCAR.

Monument Detail

Sketch

FILED

Date: 7/30/2012 by JC
This survey consists of:
Map: _____
Narrative: _____
Corner Rpt: CS 65/77-10

DOUGLAS COUNTY
SURVEYOR

Monument Set (Procedures and Description)

None

New Accessories

A 13" D. FIR. N62°E 17.5 FT scribed 1/4 S 14 RT

Location & Comments

Surveyor's Seal

Compass Declination

Firm/Agency: i.e. Engineering, Inc.



Address: 809 SE Pine St.
Roseburg, OR 97470

Party Chief: B. KVAPP

Notes:

Witness:

CS. File No 65/77-10



EXP 12-31-12