

CORNER REPORT FORM

Section 14 Township 31S Range 4W
Douglas County Date 7-2012

CORNER DESIGNATION

540500

Condition Report only
Not Found
Renewed
Unrecorded
Surveyed In
Referenced out

1/4 COR Sec 11 & 14

Previous Renewals/Surveys, etc:

MARKHAM 1959

Monument(s) & Accessories Found: (Condition and Source)

Ed 1 1/4" I. Pipe

FILED

Date: 7/30/2012 By: JC

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: CS 65/77-13

DOUGLAS COUNTY
SURVEYOR

Monument Detail

Sketch

Monument Set (Procedures and Description)

New Accessories

A 8" D. FIR S40W 6 3/4 FT scribed 1/4 S14 BT
A 12" D. FIR N50E 9 1/2 FT scribed 1/4 S11 BT

Location & Comments

CORNER IS APPROX
150' EAST OF ROAD

Compass Declination

Firm/Agency: i.e. Engineering, Inc.

Address: 809 SE Pine St.
Roseburg, OR 97470

Party Chief:

Notes:

Witness:

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Ronald A. Quimby
OREGON
JULY 14, 1978
RONALD A. QUIMBY
1654

EXP 12-31-12

C.S. File No 65/77-13