

CORNER REPORT FORM

Section 14 Township 31S Range 4W
Douglas County Date 7-2012

CORNER DESIGNATION

LINE TREE
1152 Feet North of 1/4 Cor 15/14
(Rec. 21.48 ch 1417.7)
Previous Renewals/Surveys, etc:

Condition Report only
Not Found
Renewed
Unrecorded
Surveyed In
Referenced out

Monument(s) & Accessories Found: (Condition and Source)

Fd 36" D Fir stump with 2 notches on
North side

FILED
Date: 7/30/2012 by JC
This survey consists of:
Map: _____
Narrative: _____
Corner Rpt: 65/77-14

**DOUGLAS COUNTY
SURVEYOR**

Monument Detail

Sketch

2 1/2" Alum CAP stamped Roseburg Resources
Company

Monument Set (Procedures and Description)

set 5/8" I ROD with 2 1/2" Alum CAP in
center of stump

New Accessories

A 1 1/2" D. Fir bears S69°E 10⁵ FT scribed LT BT
A 6" D. Fir bears S55°W 24² FT scribed LT BT

Location & Comments

Surveyor's Seal

Compass Declination

Firm/Agency: i.e. Engineering, Inc.

Address: 809 SE Pine St.
Roseburg, OR 97470

Party Chief: B. KUAPP

Notes: D. FIEGA

Witness:

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Ronald A. Quimby
OREGON
JULY 14, 1978
RONALD A. QUIMBY
1654

C.S. File No 65/77-14

EXP 12-31-12