

FILED

Date: 8/13/2012 By: Jc

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: CS 65/77-21

OREGON CORNER RESTORATION FORM

Section 26 Township 30 South, Range 4 West
County Douglas Date 7 August 2012

DOUGLAS COUNTY
SURVEYOR

Corner Description

SW

Section 26

Condition Report Only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

Previous Renewals / Surveys, etc.

Monument (s) & Accessories Found: (Condition and Source)

2 1/2" DCSO brass cap on iron pipe, dated 1977 with 1/2" rebar adjacent.
(Found good condition on 8-7-2012)

Maple, 17" dia., bears N.2 1/2°E., 23.1 ft., with a healed double blaze.
(Found good condition on 8-7-2012)

Maple, 27" dia., bears S.12 1/2°E., 60.2 ft., with a healed double blaze.
(Now 28" good condition on 8-7-2012)

D. Fir, 16" dia., bears N.33 1/2°W., 27.8 ft., with a healed double blaze.
(Now 20" good condition on 8-7-2012)

D. Fir, 7" dia. bears S.42 1/2°W. 9.0 ft. mkd. T30S R4W S34 BT
(Now 11" healed face, good condition on 8-7-2012)

Monument Detail

Sketch

Monument Set (Procedures and Description)

None

New Accessories

None

Location & Comments

Corner has steel post _____ Compass Declination 16° East
adjacent to it. _____ Firm/Agency Northwest Land

All BT's have red painted _____ Surveying Inc.

bands and yellow tags. _____ Address P.O. Box 2827
_____ Florence, OR 97439

_____ Party Chief Ron Rice

_____ Notes _____

_____ Witness Jason Collver

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Ronald L. Rice

OREGON
JULY 9, 2002
RONALD L. RICE
54633LS

RENEWS: 12-31-2012

C.S. FILE 65/77-21

500200