

FIRST RE-ESTABLISHMENT

DOUGLAS COUNTY
SURVEYORSection corner common to Sec. 19, 20, 29 and 30, Twp. 30 South, Range 3 East, W.M. $V=19\frac{1}{2}^\circ$

Fd. lying on stump near re-establish position of corner, the original 1x36 ins. (2.5x91 cm) iron pipe with attached G.L.O. brass cap mkd:

T30S	R3E
S19	S20
S30	S29
1928	

as recorded by H.Raymond in 1928.

I re-set said pipe 30 ins. (76 cm.) in ground, from which original bearing trees fd as follows:

Hemlock, 19 ins. (48 cm.) diam., with healed single blaze brs record; $N36^\circ E$, 27.06 ft. (8.25 M.) to center.

SE bearing tree is now gone.

Cedar, 17 ins. (43 cm.) diam., with healed single blaze, brs record; $S38^\circ W$, 61.38 ft. (18.71 M.) to center.Fir snag, 18 ins. (46 cm.) diam., containing scribe mks, including "R3ES19BT" in partially exposed face, brs. record; $N36\frac{1}{2}^\circ W$, 71.94 ft. (21.93 M.) to center.

I mk new trees CS BT, and take measurements to center of trees at lower blaze:

Hemlock, 18 ins. (46 cm.) diam., brs. $S86\frac{1}{4}^\circ E$, 97.18 ft. (29.62 M.).Hemlock, 12 ins. (30 cm.) diam., brs. $N12\frac{1}{2}^\circ W$, 39.48 ft. (12.03 M.).Corner lies about 350 ft. (107 M.) west of logging road C.N-S, and near NW corner of clear-cut unit and 30 ft. (9m.) south of the top of small ridge C. $N80^\circ E$.

October 19, 1977

B.Malotte

R.Frost

Approved By: Ed McGinty

County Sureyor