

FILED

Date: 11-6-2012 By: X

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: CS 65/77-47

OREGON CORNER RESTORATION FORM

Section 33 Township 20 South, Range 9 West
County Douglas Date 30 October 2012

DOUGLAS COUNTY
SURVEYOR

Corner Description

C1/4
Section 33

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals / Surveys, etc.

Monument (s) & Accessories Found: (Condition and Source)

Found 3-1/4" BLM brass cap on iron pipe, dated 1984
44" D. Fir bears N 63-1/4° E 52.1' – healed face
32" R. Cedar bears S 72° W 70.0' – healed face

Monument Detail

Sketch

Monument Set (Procedures and Description)

None

New Accessories

27" Maple bears S 32° E 20.8' – blazed, scribed C 1/4 S33 BT
36" Hem. bears N 63° E 40.3' – blazed, scribed C 1/4 S33 BT

Location & Comments

Corner has steel post _____ Compass Declination 16° East
 adjacent to it. _____ Firm/Agency Northwest Land
All BT's have red painted _____ Surveying Inc.
bands and yellow tags. _____ Address P.O. Box 2827
 _____ Florence, OR 97439
 _____ Party Chief Ron Rice
 _____ Notes _____
 _____ Witness Jason Collver

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Ronald L. Rice

OREGON
JULY 9, 2002
RONALD L. RICE
54633LS

RENEWS: 12-31-2012

C.S. File No 65/77-47