

OREGON CORNER RESTORATION FORM

Section 18 Township 20 South, Range 7 West
County Douglas Date 28 February 2013

FILED
Date: 3-29-2013 By: JC
This survey consists of:
Map: _____
Narrative: CS
Corner Rpt: 65/78-14
DOUGLAS COUNTY
SURVEYOR

Corner Description

CC
Section 7, 18

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals / Surveys, etc.

Monument (s) & Accessories Found: (Condition and Source)

Found: On 2-28-2013 a 2 1/2" GLO brass cap on iron pipe, dated 1954

- Fir snag, 28" dia., bears N.54° E., 37 lks. dist., with partial scribe marks visible on old bark blaze. (Missing on 2-28-2013)
- Fir 38" dia., bears S.49 1/2° E., 44 lks. dist. mkd. BT S18 T20S R7W in bark. (Found on 2-28-2013 a 38" stump – no marks)
- Fir snag 34" dia., bears S.33° E., 10 lks. dist., with partial scribe marks visible on scaled bark blaze. (Missing on 2-28-2013)
- Fir 28" dia., bears S.87° W., 31 lks. dist., plainly blazed and healed. (Found on 2-28-2013 a 28" X 5' burned fir stump)
- Hemlock 8" dia., bears N.39 3/4° E., 27 lks. dist., mkd. T20S R7W S7 CC BT. (Missing on 2-28-2013)

Monument Detail

Sketch

Monument Set (Procedures and Description)

None

New Accessories

- 17" D. Fir bears S 58° E 5.9 ft. blazed, scribed, T20S R7W S18 CC BT
- 20" D. Fir bears N 40° E 24.3 ft. blazed, scribed, T20S R7W S7 CC BT
- 19" D. Fir bears N 75° W 7.8 ft. blazed, scribed, X BT
- 18" D. Fir bears S 38° W 22.8 ft. blazed, scribed, X BT

Location & Comments

Corner has steel post _____ Compass Declination 16° East
adjacent to it. _____ Firm/Agency Northwest Land
All BT's have red painted _____ Surveying Inc.
bands and yellow tags. _____ Address P.O. Box 2827
 _____ Florence, OR 97439
 _____ Party Chief Ron Rice
 _____ Notes _____
 _____ Witness _____

Surveyor's Seal



RENEWS: 12-31-2014

C.S. FILE 65/78-14